

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|--------------------|----------------------|----------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| Buick | | | | | | |
| Passenger Vehicles | Allure | 2007-09 | Schrader | | 30016 | 62(7) |
| | | | Siemens | 15921013 | 30018 | 80(9) |
| | LaCrosse | 2007-09 | Schrader | | 30016 | 62(7) |
| | | | Siemens | 15921013 | 30018 | 80(9) |
| | LeSabre | 2007 | Schrader | 25799331 | 30026 | |
| | Lucerne | 2007 | Schrader | 25799331 | 30026 | |
| Lucerne | 2008-09 | Schrader | 15922396 | 30026 | | |
| Light Truck/ SUV | Enclave | 2008 | Siemens | 15921013 | 30018 | 80(9) |
| | Rainier | 200-07 | Schrader | 25774006 | 30016 | 62(7) |
| | Rainier(snap-in) | 2007 | Schrader | 25799331 | 30026 | |
| Cadillac | | | | | | |
| Passenger Vehicles | CTS | 2004-07 | Schrader | 25774006 | 30016 | 62(7) |
| | CTS | 2008-09 | Schrader | 15922396 | 30026 | |
| | DeVille °C | 2001-05 | Schrader | 25773946 | 30013 | 62(7) |
| | DTS | 2006 | Schrader | 15268606 | 30018 | 62(7) |
| | DTS | 2007-09 | Schrader | 25799331 | 30026 | |
| | Seville °C | 2001-04 | Schrader | 25773946 | 30013 | 62(7) |
| | STS | 2005-08 | Schrader | 25758220 | 30016 | 62(7) |
| | STS | 2009 | Schrader | 15268606 | 30018 | 62(7) |
| | XLR | 2004-09 | Schrader | 25758220 | 30016 | 62(7) |
| Light Truck/ SUV | Escalade | 2004 | Schrader | 15136883 | 30016 | 62(7) |
| | Escalade | 2005-06 | Schrader | 15114379 | 30016 | 62(7) |
| | Escalade(TRW) | 2007 | TRW | 15825475 | 30043* | 62(7) |
| | | 2008 | | | | |
| | Escalade(snap-in) | 2007-09 | Schrader | 25920615 | 30026 | |
| | Escalade | 2008 | Siemens | 25799331 | 30018 | 62(7) |
| | SRX | 2004-06 | Schrader | 25774006 | 30016 | 62(7) |
| SRX | 2007-09 | Schrader | 25799331 | 30026 | | |
| Chevrolet | | | | | | |
| Passenger Vehicles | Aveo | 2007-09 | Schrader | 15922396 | 30026 | |
| | Cobalt | 2008-09 | Siemens | 15921013 | 30018 | 80(9) |
| | Corvette | 2001-02 | Schrader | 25773946 | 30013 | 62(7) |
| | Corvette | 2003-04 | Schrader | 25773946 | 30013 | 62(7) |
| | Corvette | 2005-09 | Schrader | 25758220 | 30016 | 62(7) |
| | HHR | 2008-09 | Siemens | 15921013 | 30018 | 80(9) |
| | Impala | 2006-07 | Schrader | 15268606 | 30018 | 62(7) |
| | Impala(snap-in) | 2007-09 | Schrader | 25799331 | 30026 | |
| | Malibu | 2008 | Siemens | 15921013 | 30018 | 80(9) |
| | Malibu(snap-in) | 2008-09 | Schrader | 15922396 | 30026 | |
| | Monte Carlo | 2006-07 | Schrader | 15268606 | 30018 | 80(9) |
| | Monte Carlo(snap-in) | 2007-08 | Schrader | 25799331 | 30026 | |
| | Chevrolet | | | | | |
| | Avalanche | 2004 | Schrader | 15136883 | 30016 | 62(7) |
| | Avalanche | 2005-06 | Schrader | 15114379 | 30016 | 62(7) |
| | Avalanche(TRW) | 2007 | TRW | 15825475 | 30043* | 62(7) |
| | Avalanche(snap-in) | 2007-09 | Schrader | 25799331 | 30026 | |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|-----------------------|--------------------|----------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| Light Truck/ SUV | Avalanche | 2009 | Siemens | | 30018 | 80(9) |
| | Colorado | 2007-09 | Schrader | 15122618 | 30011 | 62(7) |
| | | | | | 30024 | |
| | Equinox | 2007 | Siemens | 15921013 | 30018 | 80(9) |
| | Equinox | 2008 | Siemens | 15921013 | 30018 | 80(9) |
| | Express | 2008 | Siemens | 15921013 | 30018 | 80(9) |
| | Express | 2008 | Schrader | 25799331 | 30026 | |
| | Silverado | 2004 | Schrader | 15136883 | 30016 | 62(7) |
| | Silverado | 2005-06 | Schrader | 15114379 | 30016 | 62(7) |
| | Silverdao(TRW) | 2007 | TRW | 15825475 | 30043* | 62(7) |
| | | | | | | 80(9) |
| | Silverdao(snap-in) | 2007-09 | Schrader | 25799331 | 30026 | |
| | Silverdao | 2007 | Siemens | | 30018 | 80(9) |
| | SSR(TPMS optional) | 2006-07 | Schrader | 25774006 | 30016 | 62(7) |
| | Suburban | 2004 | Schrader | 15136883 | 30016 | 62(7) |
| | Suburban | 2005-06 | Schrader | 15114379 | 30016 | 62(7) |
| | Suburban(TRW) | 2007 | TRW | 15825475 | 30043* | 62(7) |
| | | | | | | 80(9) |
| | Suburban(snap-in) | 2007-09 | Schrader | 25799331 | 30026 | |
| | Suburban | 2008 | Siemens | | 30018 | 80(9) |
| | Tahoe | 2004 | Schrader | 15136883 | 30016 | 62(7) |
| | Tahoe | 2005-06 | Schrader | 15114379 | 30016 | 62(7) |
| Tahoe(TRW) | 2007 | TRW | 15825475 | 30043* | 62(7) | |
| | | | | | 80(9) | |
| Traverse | 2009 | Schrader | 25920615 | 30026 | | |
| Tahoe(snap-in) | 2007-09 | Schrader | 25799331 | 30026 | | |
| Tahoe | 2007 | Siemens | | 30018 | 80(9) | |
| Trail Blazer | 2006-09 | Schrader | 25774006 | 30016 | 62(7) | |
| Uplander | 2008 | Schrader | 15268606 | 30018 | 80(9) | |
| Chrysler | | | | | | |
| Passenger Vehicles | 300 | 2005-06 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | 300 | 2007 | Siemens | 68001698AA | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | 300 | 2008 | Siemens | 68001698AA | 30018 | 71(8) |
| | 300M | 2002-04 | Schrader | 52088990AC | 30013 | 58(6.5) |
| | Concorde | 2002-04 | Schrader | 52088990AC | 30013 | 58(6.5) |
| | Crossfire | 2004 | Schrader | 52088990AC | 30013 | 58(6.5) |
| Crossfire | 2005 | Schrader | 52088990AC | 30018 | 71(8) | |
| Chrysler | | | | | | |
| | Crossfire | 2006-08 | Schrader | 52088990AC | 30013 | 35(4) |
| | Pacifica | 2004-05 | Siemens | 5127335AB-AD | 30018 | 71(8) |
| | Pacifica | 2006 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Pacifica | 2007-08 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| PT Cruiser | 2008-09 | Siemens | 56053030AB | 30018 | 71(8) | |

*Available from Ken-Tool, but not included in 30000 kit.

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|--------------------|------------------|----------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| Passenger Vehicles | Sebring | 2007-09 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Town & Country | 2002-03 | Schrader | 52088990AC | 30013 | 35(4) |
| | Town & Country | 2004-05 | Siemens | 5127335AB-AD | 30018 | 71(8) |
| | Town & Country | 2006-08 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Town & Country | 2008-09 | Siemens | 68001698AA | 30018 | 71(8) |
| Voyager | 2002-03 | Schrader | 52088990AC | 30013 | 35(4) | |
| SUV | Aspen | 2008-09 | Schrader | 56029465AB | 30018 | 71(8) |
| | | 2005-06 | Schrader | 56053030AB | 30018 | |
| Dodge | | | | | | |
| Passenger Vehicles | Avenger | 2007-09 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Caliber | 2007-09 | Siemens | 56053031AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Caravan | 2002-03 | Schrader | 52088990AC | 30013 | 35(4) |
| | Caravan | 2004-05 | Siemens | 5127335AB-AD | 30018 | 71(8) |
| | Caravan | 2006 | Siemens | 56053031AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Caravan | 2007 | Siemens | 56053031AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Caravan | 2008 | Siemens | 68001698AA | 30018 | 71(8) |
| | Challenger | 2008 | Siemens | 56029400AC | 30018 | 71(8) |
| | | | Schrader | 56053030AB | 30042* | |
| | Charger | 2006 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Charger | 2007 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Charger | 2008 | Siemens | 68001698AA | 30018 | 71(8) |
| | Grand Caravan °C | 2002-03 | Schrader | 52088990AC | 30013 | 58(6.5) |
| | Grand Caravan | 2004-05 | Siemens | 5127335AB-AD | 30018 | 71(8) |
| Grand Caravan | 2006 | Siemens | 56053030AB | 30018 | 71(8) | |
| | | Schrader | 56053030AB | 30042* | | |
| Grand Caravan | 2007 | Siemens | 56053030AB | 30018 | 71(8) | |
| | | Schrader | 56053030AB | 30042* | | |
| Grand Caravan | 2008-09 | Siemens | 68001698AA | 30018 | 71(8) | |
| Dodge | | | | | | |
| Passenger Vehicles | Intrepid °C | 2002-04 | Schrader | 52088990AC | 30013 | 58(6.5) |
| | Magnum | 2005-06 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | |
| | Magnum | 2007 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | 56053030AB | 30042* | |
| | Magnum | 2008 | Siemens | 68001698AA | 30018 | 71(8) |
| | Stratus | 2007 | Siemens | 56053030AB | 30018 | 71(8) |
| Viper | 2003-08 | Schrader | 52088990AC | 30013 | 35(4) | |
| Dakota | 2008-09 | Schrader | 56029319AA | 30018 | 71(8) | |
| Durango | 2007-08 | Schrader | 56053030AB | 30018 | 71(8) | |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|-----------------------|----------------------------|----------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| Light Truck/ SUV | Ram1500,2500,3500(non-DRW) | 2008 | Schrader | 56029319AA | 30042* | 71(8) |
| | Nitro | 2007-08 | Siemens | 56053030AB | 30018 | 71(8) |
| | Sprinter | 2007-08 | Siemens | 68006771AA | 30040* | 53(6) |
| Ford | | | | | | |
| Passenger Vehicles | Crown Victoria | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | Five Hundred | 2006-07 | Ford(band) | 6F2Z-1A189A | | |
| | Focus | 2008 | Ford(band) | 6F2Z-1A189A | | |
| | Freestar(indirect) | 2004-05 | | | | |
| | Freestar(direct) °C | 2004-05 | Schrader | 5L7T1A150AB | 30017 | 44(5) |
| | Freestar(direct) | 2006-07 | Ford(band) | 6F2Z-1A189A | | |
| | Fusion | 2008 | Ford(band) | 6F2Z-1A189A | | |
| | Mustang | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | Taurus | 2008 | Ford(band) | 6F2Z-1A189A | | |
| | Taurus X | 2008 | Ford(band) | 6F2Z-1A189A | | |
| Windstar | 2001-03 | | | | | |
| Light Truck/ SUV | E-Series | 2008 | Ford(band) | 8C2Z-1A189 | | |
| | Edge w/chrome whls | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | Edge w/o chrome whls | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | Escape & Hybrid(2006-08) | 2005-08 | Ford(band) | 6F2Z-1A189A | | |
| | Expedition °C | 2003-04 | Schrader | 4L2T1A150BA | 30017 | 44(5) |
| | Expedition °C | 2005-06 | Schrader | 5L7T1A150AB | 30017 | 44(5) |
| | Expedition | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | Explorer °C | 2002-05 | Schrader | 4L2T1A150BA | 30017 | 44(5) |
| | Explorer | 2006-08 | Ford(band) | 6F2Z-1A189A | | |
| | Explorer Sport Trac | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | F150 | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | F150 HD | 2008 | Ford(band) | 8C2Z-1A189 | | |
| | F250 Super Duty | 2008 | Ford(band) | 8C2Z-1A189 | | |
| | F350 | 2008 | Ford(band) | 8C2Z-1A189 | | |
| | F450 | 2008 | Ford(band) | 8C2Z-1A189 | | |
| | F550 | 2008 | Ford(band) | 8C2Z-1A189 | | |
| | Ranger | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| GMC | | | | | | |
| Light Truck/ SUV | Acadia | 2007-09 | Siemens | 15921013 | 30018 | 80(9) |
| | | | Schrader | | 30016 | 62(7) |
| | Canyon | 2007-09 | Schrader | 15122618 | 30024 | 62(7) |
| | Envoy | 2006-08 | Schrader | 25920635 | 30016 | 62(7) |
| | Envoy | 2009 | Schrader | 25774006 | 30016 | 62(7) |
| | Envoy(TRW) | 2007 | TRW | 15825475 | 30043* | 62(7) |
| | | | | | | 80(9) |
| | Envoy | 2008 | Schrader | 25799331 | 30026 | |
| | Savana | 2008-09 | TRW | 15825475 | 30018 | 80(9) |
| | | | | | | 80(9) |
| | Sierra | 2004 | Schrader | 15136883 | 30016 | 62(7) |
| Sierra | 2005-07 | Schrader | 15114379 | 30016 | 62(7) | |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|--------------------|----------------------|----------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| | Sierra(TRW) | 2007 | TRW | 15825475 | 30043* | 62(7) 80(9) |
| | Sierra(snap-in) | 2007 | Schrader | 25799331 | 30026 | |
| | Sierra | 2008 | Schrader | 25799331 | 30026 | |
| | Yukon | 2004 | Schrader | 15136883 | 30016 | 62(7) |
| | Yukon | 2005-06 | Schrader | 15114379 | 30016 | 62(7) |
| | Yukon(TRW) | 2007 | TRW | 15825475 | 30043* | 62(7) 80(9) |
| | Yukon(snap-in) | 2007-09 | Schrader | 25799331 | 30026 | |
| Hummer | | | | | | |
| SUV | H2 | 2008 | Schrader | 25799331 | 30026 | |
| | H3 | 2006-08 | Schrader | 15122618 | 30011 30024 | 62(7) |
| Jeep | | | | | | |
| SUV | Commander | 2006 | Siemens | 56053030AB | 30018 | 71(8) |
| | Commander | 2007 | Schrader | 56053030AB | 30018 | 71(8) |
| | Commander | 2008 | Schrader | 56029319AA | 30042* | 66(7.5) |
| | Compass | 2007-09 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | 58(6.5) |
| | Grand Cherokee °C | 2002-04 | Schrader | 52088990AC | 30013 | 64(7) |
| | Grand Cherokee | 2005 | Siemens | 56053030AB | 30018 | 66(7.5) |
| | Grand Cherokee | 2006 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | | 30042* | 66(7.5) |
| | Grand Cherokee | 2007 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | 56053030AB | 30042* | 66(7.5) |
| | Grand Cherokee | 2008 | Schrader | 56029319AA | 30042* | 66(7.5) |
| | Liberty | 2004 | Schrader | 52088990AC | 30013 | 64(7) |
| | Liberty | 2005-06 | Siemens | 56053030AB | 30018 | 71(8) |
| Schrader | | | | 30042* | 66(7.5) | |
| Liberty | 2007-08 | Siemens | 56053030AB | 30018 | 71(8) | |
| | | Schrader | | 30042* | 66(7.5) | |
| Jeep | | | | | | |
| SUV | Patriot | 2007-09 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | 56053030AB | 30042* | 58(6.5) |
| | Wrangler | 2007-08 | Siemens | 56053030AB | 30018 | 71(8) |
| | | | Schrader | 56053030AB | 30042* | |
| Lincoln | | | | | | |
| Passenger Vehicles | MKZ | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | Town Car | 2008 | Ford(band) | 6F2Z-1A189A | | |
| Light Truck/ SUV | Aviator °C | 2003-05 | Schrader | 4L2T1A150BA | 30017 | 44(5) |
| | Mark LT | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | MKX w/chrome whls. | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | MKX w/o chrome whls. | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | Navigator °C | 2003-04 | Schrader | 4L2T1A150BA | 30017 | 44(5) |
| | Navigator °C | 2005-06 | Schrader | 5L7T1A150AB | 30017 | 44(5) |
| | Navigator | 2007-08 | Ford(band) | 6F2Z-1A189A | | |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|---------------------|--------------------|---------|-------------|-----------------------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| Mercury | | | | | | |
| Passenger Vehicles | Grand Marquis | 2006-08 | Ford(band) | 6F2Z-1A189A | | |
| | Milan | 2008 | Ford(band) | 6F2Z-1A189A | | |
| | Montego | 2006-07 | Ford(band) | 6F2Z-1A189A | | |
| | Monterey(indirect) | 2004-05 | | | | |
| | Monterey(direct) | 2004-05 | Schrader | 5L7T1A150AB | 30017 | 44(5) |
| | Monterey °C | 2006-07 | Ford(band) | 6F2Z-1A189A | | |
| | Sable | 2008 | Ford(band) | 6F2Z-1A189A | | |
| SUV | Mariner | 2006-08 | Ford(band) | 6F2Z-1A189A | | |
| | Mountaineer °C | 2002-05 | Schrader | 4L2T1A150BA | 30017 | 44(5) |
| | Mountaineer | 2006-08 | Ford(band) | 6F2Z-1A189A | | |
| Pontiac | | | | | | |
| | G5 | 2008 | Siemens | 15921013 | 30018 | 80(9) |
| | G6 | 2008 | Siemens | 15921013 | 30018 | 80(9) |
| | G6(snap-in) | 2008 | Schrader | 25799331 | 30026 | |
| | G8 | 2008 | Schrader | 15922396 | 30026 | |
| | Grand Prix | 2007-08 | Schrader | | 30016 | 62(7) |
| | | | Siemens | 15921013 | 30018 | 80(9) |
| | Montana SV6 | 2008 | Schrader | 15268606 | 30018 | 80(9) |
| | Solstice | 2008-09 | Siemens | 15921013 | 30018 | 80(9) |
| | Vibe | 2005-07 | | | | |
| | Vibe | 2008-09 | Pacific | US=42607-06011 Jpn=42607-33011 | 30023 | 35(4) |
| SUV | Torrent | 2007-09 | Schrader | | 30016 | 62(7) |
| | | | Siemens | 15921013 | 30018 | 80(9) |
| Saturn | | | | | | |
| Passenger Vehicles | Astra | 2008-09 | Schrader | 13172567 | 30041* | 62(7) |
| | Aura(snap-in) | 2007-08 | Siemens | 15921013 | 30018 | 80(9) |
| | | | Schrader | 15921013 | 30016 | 62(7) |
| | Aura | 2008 | Schrader | 15922396 | 30026 | |
| | Sky | 2007-09 | Schrader | | | 62(7) |
| Siemens | | | 15921013 | 30018 | 80(9) | |
| Light Truck/ SUV | Lambda Crossover | 2007-08 | Schrader | 15268606 | 30018 | 62(7) |
| | Outlook | 2007-08 | Schrader | 15921013 | 30018 | 62(7) |
| | | | Siemens | 15921013 | 30018 | 80(9) |
| | Vue | 2007-08 | Schrader | 25799331 | 30026 | |
| Acura | | | | | | |
| Passenger Vehicles | CSX | 2008 | TRW | 42753-SNA-A83 | 30044* | 35(4) |
| | RL | 2005-08 | TRW | 06421-S3V-A04 | 30021 | 35(4) |
| | TL | 2006-08 | TRW | 06421-S3V-A04 | 30021 | 35(4) |
| | TSX | 2007-08 | TRW | 06421-S3V-A04 | 30023 | 35(4) |
| SUV | MDX | 2004-06 | TRW | 06421-S3V-A04 | 30021 | 35(4) |
| | MDX | 2007-09 | Pacific | 42753-STK-A02 | 30023 | 35(4) |
| | RDX | 2007-09 | Pacific | 42753-STK-A02 | 30023 | 35(4) |
| Audi | | | | | | |
| | A3 | 2006-09 | Siemens | 1K0907253D | 30019 | 71(8) |
| | A4&S4 | 2005-08 | Beru | 4F0907275B | | 35(4) |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|--------------------|--------------------|---------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| Passenger Vehicles | A5&S5 | 2008-09 | Siemens | 1K0907253D | 30019 | 71(8) |
| | A6(433mHz) | 2007-09 | Beru | 4D0907275B | 30022 | 35(4) |
| | A6 Allroad(433mHz) | 2001-09 | Beru | 4D0907275B | 30022 | 35(4) |
| | A6 Allroad(315mHz) | 2001-08 | Beru | 4F0907275A | 30022 | 35(4) |
| | A8&S8 | 2000-03 | Beru | 4D0907275A | 30022 | 35(4) |
| | A8&S8(433mHz) | 2003 | Beru | 4D0907275 | 30022 | 35(4) |
| | A8&S8 (315mHz) | 2004-06 | Beru | 4D0907275 | 30022 | 35(4) |
| | A8&S8 (433mHz) | 2007-09 | Beru | 4F0907275A | 30022 | 35(4) |
| | RS4 | 2007-09 | Beru | 4F0907275B | 30022 | 35(4) |
| | S6 | 2007-08 | Beru | 4F0907275B | 30022 | 35(4) |
| TT | 2007-08 | Siemens | 1K0907253D | 30019 | 71(8) | |
| SUV | Q7 | 2007-09 | Beru | 4F0907275B | 30022 | 35(4) |
| BMW | | | | | | |
| Passenger Vehicles | 323 | 2000 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 325Ci | 2001-02 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 325Ci | 2003-05 | Beru | 36118378682 | 30022 | 31(3.5) |
| | 325Ci | 2001-02 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 325Ci | 2002-03 | Beru | 36118378682 | 30022 | 31(3.5) |
| | 325Xi | 2001-02 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 325Xi | 2002-03 | Beru | 36118378682 | 30022 | 31(3.5) |
| | 328i&Ci | 2000 | Beru | 36118378681 | 30022 | 31(3.5) |
| BMW | | | | | | |
| Passenger Vehicles | 328i&Xi | 2007-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| | 330Ci | 2001-02 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 330Ci | 2002-03 | Beru | 36118378682 | 30022 | 31(3.5) |
| | 330i&Xi | 2001-02 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 330i&Xi | 2002-03 | Beru | 36118378682 | 30022 | 31(3.5) |
| | 335i & Xi | 2007-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| | 335i & Xi | 2007-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| | 525i | 2001-02 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 525i | 2002-04 | Beru | 36118378682 | 30022 | 31(3.5) |
| | 525i & Xi | 2006-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| | 528 | 2000 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 530i | 2001-02 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 530i | 2002-04 | Beru | 36118378682 | 30022 | 31(3.5) |
| | 530i & Xi | 2006-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| | 540i | 2000-02 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 540i | 2002-03 | Beru | 36118378682 | 30022 | 31(3.5) |
| | 540it | 2000 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 550i | 2006-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| | 650i | 2006-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| | 740i & Li | 2000-01 | Beru | 36118378681 | 30022 | 31(3.5) |
| | 745i & Li | 2002-03 | Beru | 36118378682 | 30022 | 31(3.5) |
| | 750i & Li | 2006-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| 760i & Li | 2006-08 | Beru | 36236771490 | 30022 | 31(3.5) | |
| 760Li | 2003 | Beru | 36118378682 | 30022 | 31(3.5) | |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|------------------------|------------------------|---------|---------------|--|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| | Alpina | 2004-08 | Beru | 36118378682 | 30022 | 31(3.5) |
| | M3 | 2001-02 | Beru | P409-S (aftermarket kit installed by dealer) | 30022 | 31(3.5) |
| | M3 | 2003-07 | Beru | 36236771490 | 30022 | 31(3.5) |
| | M5 | 2006-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| | M6 | 2006-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| | Z3 | 2002-03 | Beru | P409-S (aftermarket kit installed by dealer) | 30022 | 31(3.5) |
| | Z4 | 2006-08 | Beru | 36236771490 | 30022 | 31(3.5) |
| SUV | X3 | 2006-07 | Beru | 36236771490 | 30022 | 35(4) |
| | X5 | 2000-03 | Beru | 36146752128 | 30022 | 35(4) |
| | X5 | 2002-05 | | | | |
| | X5 | 2006-08 | Beru | 36236771490 | 30022 | 35(4) |
| Honda | | | | | | |
| Passenger Vehicles | Accord | 2008-09 | Pactific | 42753-SWA-306 | 30023 | 35(4) |
| | Civic | 2008-09 | TRW | 42753-SNA-A83 | 30044* | 35(4) |
| | Fit | 2008 | Pactific | 42753-SWA-306 | 30023 | 35(4) |
| | Odyssey Touring | 2005-07 | TRW | 06421-S3V-A04 | 30021 | 35(4) |
| | Odyssey Touring | 2008-09 | TRW | 42753-SHJ-A53 | 30044* | 35(4) |
| Honda | | | | | | |
| Passenger Vehicles | Odyssey EX,EX-L,LX | 2006-07 | TRW | 06421-SCV-A00 | 30021 | 35(4) |
| | Odyssey EX,EX-L,LX | 2008-09 | TRW | 42753-SHJ-A82 | 30044* | 35(4) |
| | S2000 | 2008 | Pactific | 42753-S2A-315 | 30023 | 35(4) |
| Light Truck/ SUV | CR-V(steel whls.) | 2007-08 | Pactific | 42753-SWA-305 | | 35(4) |
| | CR-V(alloy whls.) | 2007-09 | Pactific | 42753-SWA-306 | 30023 | 35(4) |
| | Element | 2007-09 | TRW | 06421-SCV-A00 | 30021 | 35(4) |
| | Pilot(steel whls.) | 2005-08 | TRW | 06421-S9V-A03 | 30021 | 35(4) |
| | | | | | 30021 | |
| | Pilot(alloy whls.) | 2005 | TRW | 06421-S3V-A04 | 30021 | 35(4) |
| | Pilot | 2006-08 | TRW | 06421-S3V-A04 | 30021 | 35(4) |
| | Ridgeline(steel whls.) | 2006-08 | TRW | 06421-S9V-A03 | 30021 | 35(4) |
| Ridgeline(alloy whls.) | 2006-08 | TRW | 06421-S3V-A04 | 30021 | 35(4) | |
| Hyundai | | | | | | |
| Passenger Vehicles | Accent | 2008-09 | TRW | 52933-2F000 | 30044* | 35(4) |
| | Azera | 2008-09 | Lear | 52933-2G000 | 30021 | 31-40(3.5-4.5) |
| | Elantra | 2007-09 | Lear | 52933-2G200 | 30021 | 31-40(3.5-4.5) |
| | Entourage | 2007-09 | Beru | 52933-4D200 | 30021 | 31-40(3.5-4.5) |
| | Sonata | 2007 | TRW | 52933-1F000 | 30021 | 31-40(3.5-4.5) |
| | Sonata | 2008-09 | TRW | 52933-2F000 | 30021 | 31-40(3.5-4.5) |
| | Tiburon | 2007 | TRW | 52933-1F000 | 30021 | 31-40(3.5-4.5) |
| | Tiburon | 2008 | TRW | 52933-3F000 | | 31-40(3.5-4.5) |
| SUV | Santa Fe | 2007-09 | Beru | 52933-4D200 | 30021 | 31-40(3.5-4.5) |
| | Tucson | 2006-09 | TRW | 52933-1FA00 | 30021 | 31-40(3.5-4.5) |
| | Veracruz | 2007-09 | Beru | 52933-4D200 | 30021 | 31-40(3.5-4.5) |
| Infiniti | | | | | | |
| | G35 | 2003-06 | Schrader | 40700CD001 | 30012 | 61-72(6.8-8.2) |
| | | | | | 30013 | |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|--------------------|----------------|----------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| Passenger Vehicles | G35 | 2007-08 | Schrader | 40700JA01B | 30042* | 66(7.5) |
| | G35 | 2008 | Pacific | 40700JK00B | 30042* | 66(7.5) |
| | M35 | 2006-08 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| | | | | | 30013 | |
| | M45 | 2003-04 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| | | | | | 30013 | |
| | M45 | 2006-08 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| 30013 | | | | | | |
| Q45 | 2003-05 | Schrader | 40700CD001 | 30012 | 66(7.5) | |
| | | | | 30013 | | |
| Q45 | 2006 | Schrader | 40700CD001 | 30012 | 66(7.5) | |
| | | | | 30013 | | |
| SUV | EX35 | 2008 | Schrader | 40700CD001 | 30013 | 66(7.5) |
| | FX35 | 2003-08 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| | | | | | 30013 | |
| | FX35 | 2007-08 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| | | | | | 30013 | |
| | FX45 | 2003-06 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| | | | | | 30013 | |
| | FX45 | 2007-08 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| | | | | | 30013 | |
| | QX4 | 2003 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| 30013 | | | | | | |
| QX56 | 2004 | Schrader | 40700CK002 | 30010 | 49(5.5) | |
| QX56(alloy whls.) | 2005-08 | Schrader | 40700CK001 | 30012 | 49(5.5) | |
| | | | | 30013 | | |
| QX56(steel whls.) | 2004-08 | Schrader | 40700CK002 | 30010 | 49(5.5) | |
| QX56 | 2007 | Schrader | 40700CK002 | 30010 | 49(5.5) | |
| Isuzu | | | | | | |
| SUV | Ascender | 2006-08 | Schrader | 25774006 | 30016 | 62(7) |
| | i-290 | 2007-08 | Schrader | 15122618 | 30024 | 62(7) |
| | i-370 | 2007-08 | Schrader | 15122618 | 30024 | 62(7) |
| | Rodeo | 2004 | Schrader | 52088990AC | 30013 | 35(4) |
| Jaguar | | | | | | |
| Passenger Vehicles | S Type | 2007-08 | Siemens | XR855950 | 30018 | 71(8) |
| | X Type(315mHz) | 2006-07 | Siemens | XR855950 | 30018 | 71(8) |
| | X Type(315mHz) | 2008 | Siemens | XR855950 | 30018 | 71(8) |
| | X Type(433mHz) | 2006-07 | Siemens | XR855949 | 30018 | 71(8) |
| | X Type(433mHz) | 2008 | Siemens | XR855949 | 30018 | 71(8) |
| | XJ8(315mHz) | 2004-09 | Siemens | XR855950 | 30018 | 71(8) |
| | XJ8(433mHz) | 2004-09 | Siemens | XR855949 | 30018 | 71(8) |
| | | | | | 30018 | 71(8) |
| | XJ(433mHz) | 2004-09 | Siemens | XR855949 | 30018 | 71(8) |
| | XJR | 2006-08 | Siemens | XR855950 | 30018 | 71(8) |
| | XK8 | 2007 | Siemens | RQH500460 | 30018 | 71(8) |
| | XK(315mHz) | 2006-09 | Siemens | XR855950 | 30018 | 71(8) |
| | XK(433mHz) | 2006-09 | Siemens | XR855949 | 30018 | 71(8) |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|--------------------|---------------------------|---------|-------------|-------------------------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| | XKR | 2006-09 | Siemens | XR855950 | 30018 | 71(8) |
| Kia | | | | | | |
| Passenger Vehicles | Amanti | 2006-09 | TRW | 52933-1FA00 | 30021 | 31-40(3.5-4.5) |
| | Amanti | 2006-09 | TRW | 52933-1FA00 | 30021 | 31-40(3.5-4.5) |
| | Optima | 2006 | Lear | 52933-2G200 | 30021 | 31-40(3.5-4.5) |
| | Optima | 2007-09 | Lear | 52933-2G200 | 30021 | 31-40(3.5-4.5) |
| | Rio | 2007-09 | TRW | 52933-2F200 | 30044* | 31-40(3.5-4.5) |
| | Rio & Rio5 (from 7/2/07) | 2008-09 | TRW | 52933-2F200 | 30044* | 31-40(3.5-4.5) |
| | Rondo | 2006-09 | Lear | 52933-2G200 | 30021 | 31-40(3.5-4.5) |
| | Sedona | 2006-08 | Beru | 52933-4D200 | 30021 | 31-40(3.5-4.5) |
| | Spectra | 2007-08 | TRW | 52933-2F200 | 30044* | 31-40(3.5-4.5) |
| | Spectra5 | 2008 | TRW | 52933-2F200 | 30044* | 31-40(3.5-4.5) |
| SUV | Sorento | 2007-08 | TRW | 52933-1FA00 | 30021 | 31-40(3.5-4.5) |
| | Sportage | 2006-07 | TRW | 52933-1FA00 | 30021 | 31-40(3.5-4.5) |
| | Sportage | 2008-09 | TRW | 52933-1FA00 | 30021 | 31-40(3.5-4.5) |
| Land Rover | | | | | | |
| | LR2(315mHz) | 2008 | Siemens | RQH500460 | 30018 | 71(8) |
| | LR2(433mHz) | 2008 | Siemens | RQH500470 | 30018 | 71(8) |
| | LR3 | 2005 | Beru | YBD000060 | 30022 | 71(8) |
| | LR3(315mHz) | 2006-08 | Siemens | RQH500460 | 30018 | 71(8) |
| | LR3(433mHz) | 2006-08 | Siemens | RQH500470 | 30018 | 71(8) |
| | Range Rover(315mHz) | 2006-08 | Siemens | RQH500460 | 30018 | 71(8) |
| | Range Rover(433mHz) | 2006-08 | Siemens | RQH500470 | 30018 | 71(8) |
| | Range Rover Sport(315mHz) | 2006-08 | Siemens | RQH500460 | 30018 | 71(8) |
| | Range Rover Sport(433mHz) | 2006-08 | Siemens | RQH500470 | 30018 | 71(8) |
| Lexus | | | | | | |
| Passenger Vehicles | ES 350 | 2007-09 | Pacific | 42607-33021 | 30023 | 35(4) |
| | GS 300 | 2006 | Pacific | 42607-30030 | 30023 | 35(4) |
| | GS 350 | 2007-08 | Pacific | 42607-33021 | 30023 | 35(4) |
| | GS 430 | 2005 | Pacific | Aftermarket kit installed by dealer | | 35(4) |
| | GS 430(Jun.& older) | 2006 | Pacific | 42607-30030 | 30023 | 35(4) |
| | GS 430(Jun.& newer) | 2006 | Pacific | 42607-33021 | 30023 | 35(4) |
| | GS 430 | 2007 | Pacific | 42607-33021 | 30023 | 35(4) |
| | GS 450h | 2007-09 | Pacific | 42607-33021 | 30023 | 35(4) |
| | GS 460 | 2008 | Pacific | 42607-33021 | 30023 | 35(4) |
| | IS250(Mar.& older) | 2006 | Pacific | 42607-30030 | 30023 | 35(4) |
| | IS250(Apr.& newer) | 2006 | Pacific | 42607-33021 | 30023 | 35(4) |
| | IS250 | 2007-08 | Pacific | 42607-33021 | 30023 | 35(4) |
| | IS350(Mar.& older) | 2006 | Pacific | 42607-30030 | 30023 | 35(4) |
| | IS350(Apr.& newer) | 2006-09 | Pacific | 42607-33021 | 30023 | 35(4) |
| | IS 350 | 2007-08 | Pacific | 42607-33021 | 30023 | 35(4) |
| | LS 460 | 2007-08 | Pacific | 42607-33021 | 30023 | 35(4) |
| | LS 600h | 2008-09 | Pacific | 42607-33021 | 30023 | 35(4) |
| | SC430 | 2002-05 | Pacific | 42607-24010 | 30025 | 27(3) |
| | SC430 | 2006-07 | Pacific | 42607-24010 | 30025 | 27(3) |
| | SC430 | 2007-09 | Pacific | 42607-33021 | 30025 | 35(4) |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|----------------------|---------------------------|---------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| SUV | GX470 | 2004-05 | Pacific | 42607-35010 | 30024 | 35(4) |
| | GX470(Jan 31.& older) | 2006 | Pacific | 42607-35010 | 30024 | 35(4) |
| | GX470(Feb.& newer) | 2006 | Pacific | 42607-24010 | 30024 | 35(4) |
| | GX470 | 2007-08 | Pacific | 42607-33021 | 30023 | 35(4) |
| | LX 470 | 2005 | Pacific | 42607-24010 | 30023 | 35(4) |
| | LX 470(Jul.& older) | 2006 | Pacific | 42607-24010 | 30023 | 35(4) |
| | LX 470(Aug.& newer) | 2006 | Pacific | 42607-33021 | 30023 | 35(4) |
| | LX 470 | 2007 | Pacific | 42607-33021 | 30023 | 35(4) |
| | LX 570 | 2008-09 | Pacific | 42607-33021 | 30023 | 35(4) |
| | RX 330(Jan 31.& older) | 2006 | Pacific | 42607-33021 | 30023 | 35(4) |
| | RX 330(Feb.& newer;Japan) | 2006 | Pacific | 42607-33021 | 30023 | 35(4) |
| | RX 350 | 2007-09 | Pacific | 42607-33021 | 30023 | 35(4) |
| RX 400h | 2007-09 | Pacific | 42607-33021 | 30023 | 35(4) | |
| Mazda | | | | | | |
| Passenger Vehicles | 3 | 2004 | Siemens | FE01-37-140A | 30018 | 71(8) |
| | 3 | 2005-06 | Siemens | GN3A-370-140B | 30018 | 71(8) |
| | 3 | 2007-09 | Siemens | GN3A-370-140B | 30018 | 71(8) |
| | 5 | 2006-09 | Siemens | GN3A-370-140B | 30018 | 71(8) |
| | 6 | 2005-09 | Siemens | GN3A-370-140B | 30018 | 71(8) |
| | MX-5 Miata | 2006-09 | Siemens | GN3A-370-140B | 30018 | 71(8) |
| | RX-8 | 2004 | Siemens | FE01-37-140A | 30018 | 71(8) |
| | RX-8 | 2005-09 | Siemens | GN3A-370-140B | 30018 | 71(8) |
| Mazda | | | | | | |
| Light Truck/ SUV | B Series Pickup | 2007-08 | Ford(band) | 6F2Z-1A189A | | |
| | CX-7 | 2007-09 | Siemens | GN3A-370-140B | 30018 | 71(8) |
| | CX-9 | 2007-09 | Siemens | GN3A-370-140B | 30018 | 71(8) |
| | Tribute | 2006-07 | Ford(band) | 6F2Z-1A189A | | |
| Mercedes-Benz | | | | | | |
| Passenger Vehicles | C Class | 2007-09 | Schrader | A0025409017 | 30042* | 53(6) |
| | CL Class(315mHz) | 2000-06 | Beru | A0008223406 | 30022 | 35(4) |
| | CL Class(433mHz) | 2000-06 | Beru | A0008223306 | 30022 | 35(4) |
| | CL 63AMG | 2007 | Siemens | A0025406717 | 30020 | 53(6) |
| | CL 550(315mHz) | 2007-09 | Siemens | A0025406717 | 30020 | 53(6) |
| | CL 550(433mHz) | 2007-09 | Siemens | A0025406717 | 30020 | 53(6) |
| | CL 600(315mHz) | 2007-09 | Siemens | A0025406717 | 30020 | 53(6) |
| | CL 600(433mHz) | 2007-09 | Siemens | A0025406717 | 30020 | 53(6) |
| | CLK Class(direct) | 2006-07 | Beru | A0008223406 | 30022 | 35(4) |
| | CLK Class | 2007-09 | Schrader | A0025409017 | 30042* | 53(6) |
| | CLS 63AMG | 2007 | Siemens | A0025406617 | 30020 | 53(6) |
| | CLS 650 | 2007 | Siemens | A0025406717 | 30020 | 53(6) |
| | CLS Class(direct) | 2006-09 | Siemens | A0025406617 | 30020 | 53(6) |
| | CLS Class | 2008 | Schrader | A0025406717 | 30042* | 53(6) |
| | E Class | 2000-05 | Beru | A0008223406 | 30022 | 35(4) |
| | E Class | 2006-09 | Siemens | A0025406717 | 30020 | 53(6) |
| | E Class(315mHz) | 2007-09 | Siemens | A0025406717 | 30022 | 53(6) |
| E Class(433mHz) | 2007-09 | Siemens | A0025406717 | 30020 | 53(6) | |
| S Class | 2005-06 | Beru | A0008223406 | 30022 | 35(4) | |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|--------------------------------|----------------------|----------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| SUV | S Class(315mHz) | 2007-09 | Siemens | A0025406717 | 30020 | 53(6) |
| | S Class(433mHz) | 2007-09 | Siemens | A0025406717 | 30020 | 53(6) |
| | SL Class | 2000-05 | Beru | A0008223406 | 30022 | 35(4) |
| | SL Class | 2000-05 | Beru | A0008223406 | 30022 | 35(4) |
| | SL Class | 2006-09 | Siemens | A0025406717 | 30020 | 53(6) |
| | SLK Class | 2007-09 | Schrader | A0025409017 | 30042* | 53(6) |
| | SLR McLaren | 2005-06 | Beru | A0008223406 | 30022 | 35(4) |
| | G Class | 2007-08 | Schrader | A0045409017 | 30042* | 53(6) |
| | GL Class | 2007-08 | Siemens | A0025406717 | 30020 | 53(6) |
| | ML 63AMG | 2007-08 | Siemens | A0025406717 | 30020 | 53(6) |
| | ML 320 | 2007-08 | Siemens | A0025406717 | 30020 | 53(6) |
| | ML 350 | 2006-08 | Siemens | A0025406717 | 30020 | 53(6) |
| | ML 500 | 2006-08 | Siemens | A0025406717 | 30020 | 53(6) |
| | R 320(315mHz) | 2006-08 | Siemens | A0025406717 | 30020 | 53(6) |
| | R 320(433mHz) | 2006-08 | Siemens | A0025406717 | 30020 | 53(6) |
| | R 350 | 2006-08 | Siemens | A0025406717 | 30020 | 53(6) |
| | R500 | 2006-08 | Siemens | A0025406717 | 30020 | 53(6) |
| Mini | | | | | | |
| | Cooper | 2007-09 | Beru | 36236771490 | 30022 | 35(4) |
| Mitsubishi | | | | | | |
| Passenger Vehicles | Eclipse(alloy whls.) | 2006-09 | Schrader | MN103081 | 30013 | 45-53(5-6) |
| | Eclipse(steel whls.) | 2006-07 | Schrader | 4250A030 | | 45-53(5-6) |
| | Galant | 2004-06 | Schrader | 52088990AC | 30013 | 45-53(5-6) |
| | Galant | 2007-09 | Schrader | MN103081 | 30013 | 45-53(5-6) |
| | Galant(alloy whls.) | 2008 | Schrader | MN103081 | 30013 | 45-53(5-6) |
| | Galant(steel whls.) | 2008 | Schrader | MN103081 | 30013 | 45-53(5-6) |
| | Lancer | 2007 | Siemens | 4250A225 | 30018 | 71(8) |
| | | | Schrader | 4250A225 | 30013 | |
| | Lancer | 2008-09 | Siemens | 4250A225 | 30018 | 71(8) |
| | Schrader | | 4250A225 | 30013 | | |
| SUV | Endeavor | 2004-06 | Schrader | 52088990AC | 30013 | 45-53(5-6) |
| | Endeavor | 2007-08 | Schrader | MN103081 | 30013 | 45-53(5-6) |
| | Montero | 2003-06 | Schrader | MN103081 | 30013 | 45-53(5-6) |
| | Outlander | 2007 | Schrader | 52088990AC | 30013 | 45-53(5-6) |
| | Outlander | 2007-09 | Siemens | 4250A225 | 30018 | 71(8) |
| | | | Schrader | 4250A225 | 30013 | 45-53(5-6) |
| | Raider | 2008 | Schrader | MN103081 | 30013 | 45-53(5-6) |
| Nissan | | | | | | |
| | 350Z | 2004-06 | Schrader | 40700CD001 | 30012 | 49(5.5) |
| | | | | | 30013 | |
| | 350Z | 2007-09 | Schrader | 40700JA01B | 30042* | 71(8) |
| | Altima | 2006-09 | Schrader | 40700JA01B | 30042* | 71(8) |
| | Maxima | 2006 | Schrader | 40700CK001 | 30012 | 49(5.5) |
| | | | | | 30013 | |
| Maxima(alloy whls.;Mar.&older) | 2007 | Schrader | 40700CK001 | 30012 | 49(5.5) | |
| | | | | 30013 | | |
| Maxima(alloy whls.;Apr.&newer) | 2007 | Schrader | 40700JA01B | 30042* | 71(8) | |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|---------------------|--------------------------------|----------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| Passenger Vehicles | Maxima(steel whls.;Mar.&older) | 2007 | Schrader | 40700JA01B | 30012 | 49(5.5) |
| | | | | | 30013 | |
| | Maxima(steel whls.;Apr.&newer) | 2007 | Schrader | 40700JA01B | 30042* | 71(8) |
| | Maxima | 2007-09 | Schrader | 40700JA01B | 30042* | 71(8) |
| | Quest(alloy whls.) | 2005-07 | Schrader | 40700CK001 | 30012 | 78(8.8) |
| | | | | | 30013 | |
| | Quest(steel whls.) | 2004-07 | Schrader | 40700CK002 | 30010 | 49(5.5) |
| | Quest | 2008-09 | Schrader | 40700JA01B | 30042* | 71(8) |
| | Sentra(alloy whls.) | 2007-08 | Schrader | 40700CK001 | 30012 | 78(8.8) |
| | | | | | 30013 | |
| Sentra(steel whls.) | 2007-09 | Schrader | 40700JA01B | 30042* | 71(8) | |
| Versa(steel whls.) | 2007-09 | Schrader | 40700JA01A | 30042* | 71(8) | |
| | | | 40700JA01B | | | |
| Versa(alloy whls.) | 2007-08 | Schrader | 40700CK001 | 30012 | 78(8.8) | |
| | | | | 30013 | | |
| Nissan | | | | | | |
| Light Truck/ SUV | Armada(alloy whls.) | 2005-08 | Schrader | 40700CK001 | 30012 | 49(5.5) |
| | | | | | 30013 | |
| | Armada(steel whls.) | 2005-06 | Schrader | 40700CK002 | 30010 | 49(5.5) |
| | Armada LE | 2008-09 | Schrader | 40700JA01B | 30042* | 71(8) |
| | Frontier | 2003-04 | Schrader | 40700CD001 | 30012 | 36-60(4.1-6.8) |
| | | | | | 30013 | |
| | Frontier(alloy whls.) | 2005-08 | Schrader | 40700CK001 | 30012 | 49(5.5) |
| | | | | | 30013 | |
| | Frontier(steel whls.) | 2005-07 | Schrader | 40700CK002 | 30010 | 49(5.5) |
| | Frontier(steel whls.) | 2008-09 | Schrader | 40700JA01B | 30042* | 71(8) |
| | Murano | 2003-05 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| | | | | | 30013 | |
| | Murano | 2006 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| | | | | | 30013 | |
| | Murano | 2007-09 | Schrader | 40700JA01B | 30042* | 71(8) |
| | Pathfinder | 2003-04 | Schrader | 40700CD001 | 30012 | 66(7.5) |
| | | | | | 30013 | |
| | Pathfinder(steel whls.) | 2004 | Schrader | 40700CK002 | 30010 | 49(5.5) |
| | Pathfinder | 2005-06 | Schrader | 40700CK001 | 30012 | 49(5.5) |
| | | | | | 30013 | |
| Pathfinder | 2007-09 | Schrader | 40700JA01A | 30042* | 71(8) | |
| | | | 40700JA01B | | | |
| Rogue | 2008-09 | Schrader | 40700JA01B | 30042* | 71(8) | |
| Titan(steel whls.) | 2004-07 | Schrader | 40700CK002 | 30010 | 49(5.5) | |
| Titan(alloy whls.) | 2005-08 | Schrader | 40700CK001 | 30012 | 78(8.8) | |
| | | | | 30013 | | |
| Titan(steel whls.) | 2008-09 | Schrader | 40700CK002 | 30042* | 71(8) | |
| Xterra | 2003-04 | Schrader | 40700CD001 | 30012 | 66(7.5) | |
| | | | | 30013 | | |
| Xterra | 2005-06 | Schrader | 40700CK001 | 30012 | 78(8.8) | |
| | | | | 30013 | | |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|--------------------|---------------------|---------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| | Xterra(alloy whls.) | 2006 | Schrader | 40700CK001 | 30012 | 78(8.8) |
| | | | | | 30013 | |
| | Xterra(steel whls.) | 2006-07 | Schrader | 40700CK002 | 30010 | 49(5.5) |
| | Xterra | 2007-09 | Schrader | 40700JA01A | 30042* | 71(8) |
| | | | | 40700JA01B | | |
| Porsche | | | | | | |
| Passenger Vehicles | 911 | 2005-08 | Beru | 99760602100 | 30022 | 31-40(3.5-4.5) |
| | Boxster | 2005-08 | Beru | 99760602100 | 30022 | 31-40(3.5-4.5) |
| | Carerra | 2004-08 | Beru | 99760602100 | 30022 | 31-40(3.5-4.5) |
| | Carerra GT | 2004-09 | Beru | 99760602100 | 30022 | 31-40(3.5-4.5) |
| SUV | Cayenne | 2002-06 | Beru | 95536166100 | 30022 | 31-40(3.5-4.5) |
| | Cayenne | 2007-09 | Beru | 95560602100 | 30022 | 31-40(3.5-4.5) |
| | Cayenne | 2006-09 | Beru | 99760602100 | 30022 | 31-40(3.5-4.5) |
| Saab | | | | | | |
| Passenger Vehicles | 9/3 | 2004-07 | Schrader | 13172567 | 30041* | 62(7) |
| | 9/3 | 2008-09 | Schrader | 13227143 | | 62(7) |
| | 9/5 | 2004-07 | Schrader | 13172567 | 30041* | 62(7) |
| | 9/5 | 2008-09 | Schrader | 13227143 | | 62(7) |
| | 9-7x | 2007-09 | Schrader | 25774006 | 30016 | 62(7) |
| Scion | | | | | | |
| Passenger Vehicles | TC | 2006-09 | Pacific | 42607-33011 | 30023 | 35(4) |
| | | | | | | |
| SUV | XB | 2007-09 | Pacific | 42607-33011 | 30023 | 35(4) |
| | XD | 2008 | Pacific | 42607-33011 | 30023 | 35(4) |
| Smart | | | | | | |
| | For Two | 2008 | Schrader | A0025409017 | 30042* | 35(4) |
| | | | Siemens | A0045421518 | 30020 | 53(6) |
| Subaru | | | | | | |
| Passenger Vehicles | Impreza | 2008-09 | Schrader | 28103AG01A | 30026 | |
| | Legacy | 2004 | Schrader | 28103AG00A | 30013 | 66(7.5) |
| | Legacy | 2005-07 | Schrader | 28103AG00A | 30013 | 66(7.5) |
| | Legacy | 2008-09 | Schrader | 28103AG01A | 30026 | |
| | Outback | 2004 | Schrader | 28103AG00A | 30013 | 66(7.5) |
| | Outback | 2005-07 | Schrader | 28103AG00A | 30013 | 66(7.5) |
| | Outback | 2008-09 | Schrader | 28103AG01A | 30026 | |
| SUV | B9 Tribeca | 2006-07 | Schrader | 28103AG00A | 30013 | 66(7.5) |
| | Forester | 2008-09 | Schrader | 28103AG01A | 30026 | |
| | Tribeca | 2008-09 | Schrader | 28103AG01A | 30026 | |
| Suzuki | | | | | | |
| Passenger Vehicles | Forenza | 2007-09 | Schrader | 43130-85Z00 | 30026 | |
| | Reno | 2007-09 | Schrader | 43130-85Z00 | 30026 | |
| | SX4 | 2007-09 | Schrader | 43130-54J20 | 30041* | 80(9) |
| | Verona | 2005-06 | Schrader | 43130-86Z20 | 30041* | 80(9) |
| SUV | Grand Vitara | 2007-09 | Schrader | 43130-54J20 | 30041* | 80(9) |
| | XL-7 | 2005-06 | Schrader | 43130-54J20 | 30041* | 80(9) |
| | XL-7 | 2007-09 | Schrader | 43130-78J20 | 30018 | 62(7) |
| Toyota | | | | | | |
| | Avalon | 2007-09 | Pacific | 42607-06011 | 30023 | 35(4) |
| | Camry(USA) | 2007-09 | Pacific | 42607-06011 | 30023 | 35(4) |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|---------------------|--------------------------|---------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| Passenger Vehicles | Camry(JAPAN) | 2007-08 | Pacific | 42607-33011 | 30023 | 35(4) |
| | Corolla(USA) | 2007-08 | Pacific | 42607-06011 | 30023 | 35(4) |
| | Corolla(JAPAN) | 2007-09 | Pacific | 42607-33011 | 30023 | 35(4) |
| | Matrix(USA) | 2007-09 | Pacific | 42607-06011 | 30023 | 35(4) |
| | Matrix(JAPAN) | 2007-09 | Pacific | 42607-33011 | 30023 | 35(4) |
| | Prius | 2006-08 | Pacific | 42607-33011 | 30023 | 35(4) |
| | Sienna | 2007-09 | TRW | 42607-0C050 | 30023 | 35(4) |
| | Solara | 2006-08 | Pacific | 42607-06011 | 30023 | 35(4) |
| | Yaris | 2008 | Pacific | 42607-33011 | 30023 | 35(4) |
| Toyota | | | | | | |
| Light Truck/ SUV | 4Runner | 2004-05 | Pacific | 42607-35010 | 30024 | 35(4) |
| | 4Runner(Jan 31.& older) | 2006 | Pacific | 42607-33011 | 30023 | 35(4) |
| | 4Runner(Feb.& Mar.) | 2006 | Pacific | 42607-33011 | 30023 | 35(4) |
| | 4Runner(Apr.-May) | 2006 | Pacific | 42607-33011 | 30023 | 35(4) |
| | 4Runner(Jun.&newer) | 2006 | Pacific | 42607-33011 | 30023 | 35(4) |
| | 4Runner | 2007-09 | Pacific | 42607-33011 | 30023 | 35(4) |
| | FJ Cruiser | 2008-09 | Pacific | 42607-33011 | 30023 | 35(4) |
| | Highlander | 2007-09 | Pacific | 42607-33011 | 30023 | 35(4) |
| | Land Cruiser | 2005 | Pacific | 42607-33011 | 30023 | 35(4) |
| | Land Cruiser(Jul.&older) | 2006 | Pacific | 42607-33021 | 30023 | 35(4) |
| | Land Cruiser(Aug.&newer) | 2006 | Pacific | 42607-33021 | 30023 | 35(4) |
| | Land Cruiser | 2007 | Pacific | 42607-33021 | 30023 | 35(4) |
| | Land Cruiser | 2008-09 | Pacific | 42607-33011 | 30023 | 35(4) |
| | RAV4 | 2006 | Pacific | 42607-33011 | 30023 | 35(4) |
| | RAV4 | 2007-09 | Pacific | 42607-33021 | 30023 | 35(4) |
| | Sequoia | 2004 | Pacific | 42607-35010 | 30023 | 35(4) |
| | Sequoia(20°;alloy whls.) | 2005 | Pacific | 42607-35010 | 30024 | 35(4) |
| | Sequoia(40°) | 2005 | Pacific | 42607-35010 | 30024 | 35(4) |
| | Sequoia(20°;alloy whls.) | 2006 | TRW | 42607-0C050 | 30024 | 35(4) |
| | Sequoia(40°) | 2006 | TRW | 42607-0C020 | 30024 | 35(4) |
| | Sequoia(20°;alloy whls.) | 2007 | TRW | 42607-0C050 | 30024 | 35(4) |
| | Sequoia(40°) | 2007 | TRW | 42607-0C020 | 30024 | 35(4) |
| | Sequoia(20°) | 2008-09 | TRW | 42607-0C050 | 30024 | 35(4) |
| | Sequoia(40°) | 2008 | TRW | 42607-0C060 | 30024 | 35(4) |
| | Tacoma(20°;alloy whls.) | 2005 | Pacific | 42607-AD020 | 30024 | 35(4) |
| | Tacoma(40°;steel whls.) | 2005 | Pacific | 42607-04010 | 30024 | 35(4) |
| | Tacoma(20°;Jul.&older) | 2006 | Pacific | 42607-AD020 | 30024 | 35(4) |
| | Tacoma(20°;Aug.&newer) | 2006 | Pacific | 42607-06011 | 30024 | 35(4) |
| | Tacoma(40°) | 2006 | Pacific | 42607-04010 | 30024 | 35(4) |
| | Tacoma(20°) | 2007 | Pacific | 42607-06011 | 30024 | 35(4) |
| | Tacoma(40°) | 2007 | Pacific | 42607-04010 | 30024 | 35(4) |
| | Tacoma(20°) | 2008-09 | Pacific | 42607-06011 | 30024 | 35(4) |
| | Tacoma(40°) | 2008-09 | Pacific | 42607-04010 | 30024 | 35(4) |
| | Tundra(20°) | 2005-06 | TRW | 42607-0C020 | 30024 | 35(4) |
| | Tundra(40°) | 2005-06 | TRW | 42607-0C010 | 30024 | 35(4) |
| | Tundra(20°) | 2007-09 | TRW | 42607-0C050 | 30024 | 35(4) |

| Make | Model | Year | Sensor Mfg. | OEM Sensor Part No. | Ken Tool Kit No. | Torque |
|--------------------|---------------|---------------|-------------|---------------------|------------------|-----------------------------|
| | | | | | | In/Lbs (N.m.) Sensor Nut |
| | Tundra(40°) | 2007-09 | TRW | 42607-0C060 | 30024 | 35(4) |
| Volkswagen | | | | | | |
| Passenger Vehicles | EOS | 2007-09 | Siemens | 1K0907253D | 30019 | 71(8) |
| | GLI | 2008 | Siemens | 1K0907253D | 30019 | 71(8) |
| | GTI | 2006-09 | Siemens | 1K0907253D | 30019 | 71(8) |
| | Jetta | 2005-09 | Siemens | 1K0907253D | 30019 | 71(8) |
| | New Beetle | 2007 | Siemens | 1K0907253D | 30019 | 71(8) |
| Volkswagen | | | | | | |
| Passenger Vehicles | New Beetle | 2008 | Siemens | 1K0907253D | 30019 | 71(8) |
| | Passat | 2006-09 | Siemens | 1K0907253D | 30019 | 71(8) |
| | Phaeton | 2002-04 | Beru | 4D0907275 | 30022 | 62(7) |
| | Phaeton | 2005-07 | Beru | 4F0907275B | 30022 | 62(7) |
| | R32 | 2008 | Siemens | 1K0907253D | 30019 | 71(8) |
| | Rabbit | 2007-09 | Siemens | 1K0907253D | 30019 | 71(8) |
| SUV | Touareg2 | 2007-09 | Beru | 4F0907275B | 30022 | 62(7) |
| Volvo | | | | | | |
| Passenger Vehicles | C30 | 2008-09 | Siemens | 30666931 | 30018 | 71(8) |
| | C70 | 2007-09 | Siemens | 30666931 | 30018 | 71(8) |
| | S40 | 2007-09 | Siemens | 30666931 | 30018 | 71(8) |
| | S60 (315Mhz) | 2005-07 | Schrader | 8651700 | 30041* | 44(5) |
| | S60 (433Mhz) | 2008-09 | Siemens | 30666931 | 30018 | 71(8) |
| | S80 (315Mhz) | 2005-06 | Schrader | 8651700 | 30041* | 44(5) |
| | S80 (433Mhz) | 2007-09 | Siemens | 30666931 | 30018 | 71(8) |
| | V50 | 2007-08 | Siemens | 30666931 | 30018 | 71(8) |
| | V70 (315Mhz) | 2005-07 | Schrader | 8651700 | 30041* | 44(5) |
| | V70 (433Mhz) | 2008-09 | Siemens | 30666931 | 30018 | 71(8) |
| | XC70 (315Mhz) | 2005-07 | Schrader | 8651700 | 30041* | 44(5) |
| | XC70 (433Mhz) | 2008-09 | Siemens | 30666931 | 30018 | 71(8) |
| | SUV | XC90 (315Mhz) | 2005-07 | Schrader | 8651700 | 30041* |
| XC90 (433Mhz) | | 2008-09 | Schrader | 31200923 | 30041* | 44(5) |